Crusher Plant



Return to Index

Wash Plant



Conveyance through enclosed hood control point

Aggregate begins washing process, product is fully immersed at this point and remainder of washing process


JAW PLANT
1
2
3
4
5
PRI. SCREEN
STR CONE
SCRN. 2
SHT. HEAD CONE
SCRN 3
(x6) = 8 TOTAL
= CONTROL POINT H_2O
= CONTROL POINT - ENCLOSED HOOD
= PRIMARY/NON CRUSH MATERIAL TRANS. POINT (5)



□ = CONTROL POINT
ENCLOSED HOOD

ALL TRANSFER POINTS MOVE/CONVEY WET, PROCESSED AGGREGATE (> 3% H_2O)