		MA is delegated the	
	Doub C4 National Envisoiry Standard for Harandova Air Ballytanta (NESHAD)	following standards for all sources ¹ .	
	Part 61 National Emission Standard for Hazardous Air Pollutants (NESHAP)		
Subpart	Description	Delegated	Comments
Α	General Provisions		
В	Radon Emissions from Underground Uranium Mines		
С	Beryllium	Х	
D	Beryllium Rocket Motor Firing	X	
E	Mercury	Х	
F	Vinyl Chloride	Х	
Н	Radionuclides Other Than Radon from Department of Energy Facilities		
	Radionuclide Emissions from Federal Facilities Other Than the Nuclear Regulatory		
1	Commission Licensees and Not Covered by Subpart H		
J	Equipment Leaks (Fugitive emission Sources) of Benzene		
K	Elemental Phosphorus Plants		
L	Coke By-Product Recovery Plants		
М	Asbestos	Х	
N	Inorganic Arsenic Emissions from Glass Manufacturing Plants	Х	
0	Inorganic Arsenic Emissions from Primary Copper Smelters		
	Inorganic Arsenic Emissions from Arsenic Trioxide and Metallic Arsenic Production		
Р	Facilities		
Q	Radon Emissions from the Department of Energy Facilities		
R	Radon Emissions from Phosphogypsum Stacks		
Т	Radon Emissions from the Disposal of Uranium Mill Tailings		
V	Equipment Leaks (Fugitive Emission Sources)		
W	Radon Emissions from Operating Mill Tailings		
Υ	Benzene Emissions from Benzene Storage Vessels		
BB	Benzene Emissions from Benzene Transfer Operations		
FF	Benzene Waste Operations		

^{1.} See 61 FR 3827.