

Appendix B
NEIC Inspection Photographs
(74 pages)



| Attributes | |
|-------------|---|
| File Name | P4040001.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Waiawa shaft infiltration tunnel |
| Author | David Parker |
| Date/Time | 4/4/2022 3:43:02 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040002.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Waiawa shaft pump #3 (labelled #4) |
| Author | David Parker |
| Date/Time | 4/4/2022 3:51:42 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040003.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Waiawa shaft pump #2 wiring |
| Author | David Parker |
| Date/Time | 4/4/2022 3:55:39 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040004.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Waiawa shaft pump #2 flaking paint |
| Author | David Parker |
| Date/Time | 4/4/2022 3:56:12 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040005.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Flaking paint on wall in Waiawa shaft |
| Author | David Parker |
| Date/Time | 4/4/2022 4:03:34 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040006.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Waiawa shaft sump with steel plate cover |
| Author | David Parker |
| Date/Time | 4/4/2022 4:10:05 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040007.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red can of used oily rags in workshop |
| Author | David Parker |
| Date/Time | 4/4/2022 4:14:55 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040008.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | 10 L unlabeled tanks at Waiawa |
| Author | David Parker |
| Date/Time | 4/4/2022 4:32:31 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040009.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | 330 gal sodium hypochlorite tank at Waiawa |
| Author | David Parker |
| Date/Time | 4/4/2022 4:35:01 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040010.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Waiawa fluoride tanks unlabeled |
| Author | David Parker |
| Date/Time | 4/4/2022 4:41:47 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4040011.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Fluoride & chlorine feed lines at Waiawa |
| Author | David Parker |
| Date/Time | 4/4/2022 4:49:14 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050012.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa shaft infiltration tunnel #1 |
| Author | David Parker |
| Date/Time | 4/5/2022 11:50:38 AM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050013.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa shaft infiltrations tunnel #2 |
| Author | David Parker |
| Date/Time | 4/5/2022 11:52:43 AM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050014.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa shaft infiltration tunnel #3 |
| Author | David Parker |
| Date/Time | 4/5/2022 11:53:32 AM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050015.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa shaft pump #1 air relief valve |
| Author | David Parker |
| Date/Time | 4/5/2022 12:04:59 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050016.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa shaft chlorine tank |
| Author | David Parker |
| Date/Time | 4/5/2022 12:16:29 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |


NEICVP1463E01



| Attributes | |
|-------------|---|
| File Name | P4050018.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa shaft reagent bottles |
| Author | David Parker |
| Date/Time | 4/5/2022 12:23:42 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050019.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa booster pump 2 oil leak |
| Author | David Parker |
| Date/Time | 4/5/2022 12:43:48 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050020.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa booster pump 1 service tag |
| Author | David Parker |
| Date/Time | 4/5/2022 12:46:27 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050021.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa booster pump 1 oil |
| Author | David Parker |
| Date/Time | 4/5/2022 12:49:28 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050022.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Halawa booster pumps 1 & 2 air relief valves |
| Author | David Parker |
| Date/Time | 4/5/2022 12:50:25 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050023.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank S-325 overflow drain |
| Author | David Parker |
| Date/Time | 4/5/2022 1:24:33 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050024.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank S-325 exterior & vegetation |
| Author | David Parker |
| Date/Time | 4/5/2022 1:29:10 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050025.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank S-326 overflow flapper |
| Author | David Parker |
| Date/Time | 4/5/2022 1:32:17 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050026.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tanks S-325 & S-326 ladders |
| Author | David Parker |
| Date/Time | 4/5/2022 1:34:41 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050027.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank S-325 baffled vent |
| Author | David Parker |
| Date/Time | 4/5/2022 1:36:43 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050028.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank S-326 paint with moisture pockets |
| Author | David Parker |
| Date/Time | 4/5/2022 1:41:35 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050029.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank 684 vegetation on roof |
| Author | David Parker |
| Date/Time | 4/5/2022 1:59:08 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050030.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank 684 roots from ironwood trees |
| Author | David Parker |
| Date/Time | 4/5/2022 2:01:32 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050031.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank 684 vegetation growing over roof |
| Author | David Parker |
| Date/Time | 4/5/2022 2:04:28 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050032.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank 684 vegetation growing beside pad |
| Author | David Parker |
| Date/Time | 4/5/2022 2:11:11 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050033.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Camp Smith tank 684 cracking caulk |
| Author | David Parker |
| Date/Time | 4/5/2022 2:15:03 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050034.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill ADIT 3 sump photo 1 |
| Author | David Parker |
| Date/Time | 4/5/2022 5:26:52 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050035.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill ADIT 3 sump photo 2 |
| Author | David Parker |
| Date/Time | 4/5/2022 5:27:06 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050036.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill shaft map |
| Author | David Parker |
| Date/Time | 4/5/2022 5:34:41 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050037.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill shaft infiltration gallery #1 |
| Author | David Parker |
| Date/Time | 4/5/2022 5:38:52 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050038.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill shaft infiltration gallery #2 |
| Author | David Parker |
| Date/Time | 4/5/2022 5:40:00 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050039.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill shaft water piping |
| Author | David Parker |
| Date/Time | 4/5/2022 5:53:10 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |

Joint Base Pearl Harbor-Hickam Public Water System
Pearl Harbor, Hawaii



| Attributes | |
|-------------|---|
| File Name | P4050041.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill shaft booster pump 1 to Red Hill tank air relief valve |
| Author | David Parker |
| Date/Time | 4/5/2022 6:07:48 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050042.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill 36" line to Pearl Harbor tunnel |
| Author | David Parker |
| Date/Time | 4/5/2022 6:24:32 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050043.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Line to Red Hill tanks |
| Author | David Parker |
| Date/Time | 4/5/2022 6:25:07 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050044.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Gate valve to Red Hill tanks |
| Author | David Parker |
| Date/Time | 4/5/2022 6:25:53 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050045.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Valve on AFFF line that was broken photo 1 |
| Author | David Parker |
| Date/Time | 4/5/2022 6:33:35 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4050046.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Valve on AFFF line that was broken photo 2 |
| Author | David Parker |
| Date/Time | 4/5/2022 6:39:21 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060047.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-2 access hatch |
| Author | David Parker |
| Date/Time | 4/6/2022 12:02:59 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060048.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-2 rust on access hatch hinge |
| Author | David Parker |
| Date/Time | 4/6/2022 12:05:39 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060049.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-2 roof access hatch |
| Author | David Parker |
| Date/Time | 4/6/2022 12:19:19 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060050.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-2 roof |
| Author | David Parker |
| Date/Time | 4/6/2022 12:21:12 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060051.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-2 roof center support |
| Author | David Parker |
| Date/Time | 4/6/2022 12:24:16 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060052.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-2 roof vent photo 1 |
| Author | David Parker |
| Date/Time | 4/6/2022 12:24:27 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060053.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-2 roof vent photo 2 |
| Author | David Parker |
| Date/Time | 4/6/2022 12:24:36 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060054.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-1 rust repairs |
| Author | David Parker |
| Date/Time | 4/6/2022 12:34:40 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060055.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Tank S-1 AMR GAC piping support |
| Author | David Parker |
| Date/Time | 4/6/2022 12:40:12 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060056.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Fill line for tanks S-1 & S-2 |
| Author | David Parker |
| Date/Time | 4/6/2022 12:48:15 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060057.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | S-1 tank roof hatch |
| Author | David Parker |
| Date/Time | 4/6/2022 1:02:26 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060058.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | S-1 tank inside of roof hatch |
| Author | David Parker |
| Date/Time | 4/6/2022 1:02:56 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060059.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | S-1 tank roof |
| Author | David Parker |
| Date/Time | 4/6/2022 1:04:12 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060060.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | S-1 tank upper side wall |
| Author | David Parker |
| Date/Time | 4/6/2022 1:06:31 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060061.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | S-2 tank foundation |
| Author | David Parker |
| Date/Time | 4/6/2022 1:07:44 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060062.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | S-2 tank side bulge photo 1 |
| Author | David Parker |
| Date/Time | 4/6/2022 1:08:41 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060063.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | S-2 tank side bulge photo 2 |
| Author | David Parker |
| Date/Time | 4/6/2022 1:10:23 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060064.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill upper tank foundation |
| Author | David Parker |
| Date/Time | 4/6/2022 2:00:51 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060065.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill upper tank fencing |
| Author | David Parker |
| Date/Time | 4/6/2022 2:06:53 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060066.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill lower tank bolt covers |
| Author | David Parker |
| Date/Time | 4/6/2022 2:15:51 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060067.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill lower tank interior |
| Author | David Parker |
| Date/Time | 4/6/2022 2:22:30 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060068.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill lower tank hatch |
| Author | David Parker |
| Date/Time | 4/6/2022 2:23:42 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060069.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill lower tank overflow photo 1 |
| Author | David Parker |
| Date/Time | 4/6/2022 2:28:53 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060070.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill lower tank overflow photo 2 |
| Author | David Parker |
| Date/Time | 4/6/2022 2:30:25 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060071.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill fence gap between tanks |
| Author | David Parker |
| Date/Time | 4/6/2022 2:32:50 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060072.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill lower tank vegetation below stairs photo 1 |
| Author | David Parker |
| Date/Time | 4/6/2022 2:38:44 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4060073.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | Red Hill lower tank vegetation below stairs photo 2 |
| Author | David Parker |
| Date/Time | 4/6/2022 2:38:55 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |



| Attributes | |
|-------------|---|
| File Name | P4080091.JPG |
| Title | Joint Base Pearl Harbor-Hickam |
| Description | JBPHH Boneyard booster pumps |
| Author | David Parker |
| Date/Time | 4/8/2022 3:37:20 PM |
| Comment | Time of photography was 4 hours prior to the time indicated by the camera |
| Make | OLYMPUS CORPORATION |
| Model | TG-6 |